



Apple IIGS

#82: Controlling the Control Manager

Revised by: Matt Deatherage

November 1990

Written by: Dave Lyons

May 1990

This Technical Note describes an anomaly in the `NewControl2` call in System Software 5.0.2 and provides a solution.

Changes since May 1990: Noted that System Software 5.0.3 fixes this anomaly.

This Note formerly advised of a problem with `NewControl2`—the current port was not set before adding the controls, which gave unpredictable results. System Software 5.0.3 and later fix this problem.